

# INSPECTION SERVICES

## End Area Inspection On Drill Collars, Hevi-Wate<sup>®</sup>, Subs, etc.

### Description Of Service Performed on Rack or Trip Inspections

Standard A.P.I. End Area Inspection: Record Dimensions, Visual & Blacklight Connection, Check Shoulders for damages, Profile Threads Refacing (Sandpaper type)



## Premium Class Drill Pipe Inspection

### Description Of Service

Category 3: Visual Connection & Tube, Dimensional 1, O.D. Gage, UT Wall Thickness, Electromagnetic 1 Tube Run

Category 4: Visual Connection & Tube, Dimensional 2, O.D. Gage, UT Wall Thickness, Electromagnetic 1 Tube Run, MPI Slip/Upset

Category 5: Visual Connection & Tube, Dimensional 2, Blacklight Connection, O.D. Gage, UT Wall Thickness, Electromagnetic 1 Tube Run, MPI Slip/Upset, UT Slip/Upset Refacing (Sandpaper type)

- Dry Iron Powder Blade Area
- Dye Penetrant for Non Magnetic End Area and Blade Inspection
- Clean & Visual Unused Ends
- Drilling Motor Inspection
- Complete Drilling Jar
- Borescope I.D.
- Hevi-Wate<sup>®</sup> Drill Pipe Upsets
- Stabilizer Blade Upsets
- Surface Equipment (Block, Hooks, Bails Elevators, Slips, Rig Pins)
- Ultrasonic Derrick Inspection
- Ultrasonic Top Drive
- Top Drive (Ears, Connections)
- Derrick Weld Area Inspection

**We offer drill pipe and collar inspections performed in accordance with A.P.I. specifications using state-of-the-art equipment.**